

# General Environmental Incident Summary

**Incident:** 3883      **Date/Time Notice:** 8/26/2015      1000      **DEM Incident No:**  
**Responsible Party:** BC Excavating  
**Date Incident:** 8/25/2015      **Time Incident:** 0900      **Duration:** 5 minutes  
**County:** Williams      **Twp:** 154      **Rng:** 101      **Sec:** 17      **Qtr:**  
**Lat:** 48.16034      **Long:** -103.69840      **Method:** Interpolation from map  
**Location Description:** South Ridge Apartments, 3701 7th Street West Williston 58801

**Submitted By:** Andrew Pringle      **Affiliation:**  
**Address:** 700 7th Street S  
**City:** Fargo      **State:** ND      **Zip:** 58103

## Received By:

**Contact Person:** Steve Meglich  
700 7th Street S  
Fargo, ND 58103

**Distance Nearest Occupied Building:** 2500 Feet      **Release Contained:** Yes

**Type of Incident:** Fuel Truck Equipment Failure

**Description of Released Contaminant:** Offroad Diesel Fuel

**Volume Spilled:** 50.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

During refueling of generator near job shack, the fuel truck's PTO pump failed allowing fuel to spill out of it.

## Risk Evaluation:

No immediate risk is anticipated due to spill size and speed of containment.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Potential environmental impact is expected only to the soil that was exposed to the spill. This soil will be disposed of with the absorptive material by the disposal service.

## Action Taken or Planned:

Immediately after discovery of leak, the perimeter was bermed with soil on site, after it was contained granular oil absorption material was placed in the bermed area to absorb the fuel. Next a poly lined containment area was built and the absorbed material was placed in there and covered until it can be picked up by a disposal service.

**Wastes Disposal Location:** A disposal service has been contacted to pick up the material.

## Agencies Involved:

## **Updates**

---

**Date:** 9/1/2015    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Volume:**

**Notes:**

Release impacted surrounding area. Followup is required.

---

**Date:** 9/11/2015    **Status:** Inspection

**Author:** Kangas, Kathleen

**Updated Volume:**

**Notes:**

On-site 09/09/2015 at 10:00 am. Met company representative. Spill has been cleaned up. Material went to IHD landfill. NOTE: Directions to the location - Head towards Menards in Williston, at the second roundabout take a Left and go back about a block to a block and half. Spill occurred on left on-site, about 25 feet in from road.