

General Environmental Incident Summary

Incident: 3945 **Date/Time Notice:** 10/22/2015 1010 a **DEM Incident No:**
Responsible Party: Tecton Products
Date Incident: 10/22/2015 **Time Incident:** 0930am **Duration:** 120 minutes
County: Cass **Twp:** 140 **Rng:** 49 **Sec:** 34 **Qtr:** SW NW NW
Lat: 46.89763 **Long:** -96.85786 **Method:** Interpolation from map
Location Description: 4401 15th Avenue N
Fargo, ND

Submitted By: Brett Becker **Affiliation:** Employee
Address: P.O. Box 2712
4401 15th Ave N
City: Fargo **State:** ND **Zip:** 58102

Received By:

Contact Person: Brett Becker
P.O. Box 2712
4401 15th Ave N
Fargo, ND 58102

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Hydraulic fluid

Volume Spilled: 2.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

The hydraulic system on a vendors tractor ruptured releasing approximately two gallons of material

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

None

Action Taken or Planned:

The hydraulic fluid was covered with sorbent rags. The hydraulic fluid was absorbed immediately.

Wastes Disposal Location: OSI Inc.

Agencies Involved:

Updates

Date: 10/22/2015 **Status:** Reviewed - No Action Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Hunter Hubrig with Fargo Health will be checking site later today. Minimal amount of fluid released. No further follow-up required at this time.