

General Environmental Incident Summary

Incident: 3973 **Date/Time Notice:** 12/1/2015 1100 **DEM Incident No:**

Responsible Party: Justice Oilfield Water Service Inc.

Date Incident: 12/1/2015 **Time Incident:** 0900 **Duration:**

County: Divide **Twp:** 162 **Rng:** 99 **Sec:** 35 **Qtr:**

Lat: 48.81575 **Long:** -103.49560 **Method:** Interpolation from map

Location Description: 147th Ave. 1 mile north of Ames Fresh water depot north of highway 5.

Submitted By: tracy justice

Affiliation:

Address: P.O. Box 44

City: Dagmar

State: MT

Zip: 59219

Received By:

Contact Person: Tracy Justice
P.O. Box 44
Dagmar, MT 59219

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Tank Leak

Description of Released Contaminant: salt water into ditch into containment dike.

Volume Spilled: 4.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Trailer tipped into ditch. Water recovered off trailer and some came out the hatch at time of off loading by another truck. Trailer itself was not opened up in the rollover. Contained into dike built underneath hatch.. Sucked up with the other truck and 1" hose.

Risk Evaluation:

none.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

none as it was recovered from the small containment dike.

Action Taken or Planned:

Spill contained into dike and sucked up by the other truck off loading tipped trailer. Nothing on ground on completion. Reported to Divide County Sheriff and Emergency Management of Divide County (Jody)at 701-965-6361. He told me to file this report.

Wastes Disposal Location: taken to a salt water disposal.

Agencies Involved: Local Law Enforcement, Local Emergency Manager

Updates

Date: 12/3/2015 **Status:** Inspection

Author: Souder, Taylor

Updated Volume:

Notes:

Arrived on location of release and took photos. Release is visible on gravel roadway and in ditch. Along with photos, I took a soil sample about 3 feet from the gravel road. Soil sample was 0-6 inches and taken at 1500 PM. GPS coordinates of sample can be pulled from photos.

Date: 12/3/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

Received a return phone call from the Divide County emergency manager who let me know that the release had impacted the area and will need to be cleaned up. NDDoH inspector in transit to inspect site today. Photos of the release included with email and added to folder.

Date: 1/19/2016 **Status:** Correspondence

Author: Souder, Taylor

Updated Volume:

Notes:

Received lab results, they can be found in the report folder. Levels are within NDDoH guidelines but very close to the 250 ppm cut off. Follow up in the summer months to assess vegetation growth.