

General Environmental Incident Summary

Incident: 3983 **Date/Time Notice:** 12/17/2015 1325 **DEM Incident No:**
Responsible Party: ONEOK Rockies Midstream, LLC
Date Incident: 12/16/2015 **Time Incident:** 1000 **Duration:** 30 minutes
County: Dunn **Twp:** 147 **Rng:** 96 **Sec:** 19 **Qtr:** NE
Lat: 47.54253 **Long:** -102.95960 **Method:** Navigation quality GPS
Location Description: ONEOK Big Gulch Compressor Station
Kildeer, ND 58640

Submitted By: Kevin Windstrup **Affiliation:** ONEOK Senior Environmental Engi
Address: 100 W 5th St.
City: Tulsa **State:** OK **Zip:** 74103

Received By:

Contact Person: Kevin Windstrup
2700 Lincoln Ave. SE
Sidney, ND 59270

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Hose leak

Description of Released Contaminant: 70% water/30% propylene glycol mixture

Volume Spilled: 1.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Pin-hole leak discovered in ground-warming heating hose underneath insulating blanket.

Risk Evaluation:

none

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

none - all contaminated soil was excavated and will be properly disposed.

Action Taken or Planned:

Upon discovery, release was immediately stopped, contaminated soil was excavated and placed into an approved container for disposal, and hose was repaired.

Wastes Disposal Location: Approved local landfill.

Agencies Involved:

Updates

Date: 12/17/2015 **Status:** Reviewed - No Action Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Release of small amount of fluid remained on location. Impacted material was removed. No further followup required.