

General Environmental Incident Summary

Incident: 4001 **Date/Time Notice:** 1/19/2016 1600 **DEM Incident No:**

Responsible Party: Farrington Trucking

Date Incident: 1/16/2016 **Time Incident:** 2000 **Duration:**

County: McKenzie **Twp:** 150 **Rng:** 95 **Sec:** 12 **Qtr:**

Lat: 47.82216 **Long:** -102.78140 **Method:** Interpolation from map

Location Description: Approximately 1.25 miles north of Highway 73 on 102nd Ave NW, Keene

Submitted By: Amber Senn

Affiliation: TriMedia Environmental & Engineer

Address: 31 36th Ave. NW

City: Minot

State: ND

Zip: 58703

Received By:

Contact Person: John Farrington
31283 County Highway 23
Akeley, MN 56433

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: produced water

Volume Spilled: 7.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Truck hauling production water slid downhill and off-road.

Risk Evaluation:

None

of Fatalities:

of Injuries:

Affected Medium: 04 - water and soil

Potential Environmental Impacts:

Approximately 25 ft by 20 ft area on east side of 102nd Ave NW and 45 ft by 45 ft area on western side of 102nd Ave NW. Spill occurred on top of frozen water and snow.

Action Taken or Planned:

The remaining fluids in the truck were immediately vacuumed out, approximately 113 bbls. The fluid on the ground was vacuumed. Attempted to dam the culvert beneath the road at the site of

Wastes Disposal Location: Secure Energy Services

Agencies Involved: BLM

Updates

Date: 1/19/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 7 barrels of production water were released along the road ditch during a truck accident. More followup needed.

Date: 2/22/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Espe, Brady

Updated Volume:

Notes:

Went by the area last Wednesday and could not find the exact area of spill because of recent snowfall. I also noticed the area was within tribal borders. Called the contact number and requested information on the site. Received the report from the company. Report indicated that the spill took place within the tribal lands of the MHA Nation. Talked to the contact; she has been working with personnel from the MHA Nation on the cleanup. The MHA Nation has the lead on this cleanup.