

# General Environmental Incident Summary

**Incident:** 4034      **Date/Time Notice:** 3/4/2016      1345      **DEM Incident No:**  
**Responsible Party:** Johnson Bros.  
**Date Incident:** 2/23/2016      **Time Incident:** 1800      **Duration:** 5 minutes  
**County:** Williams      **Twp:** 153      **Rng:** 101      **Sec:** 6      **Qtr:**  
**Lat:** 48.10970      **Long:** -103.72900      **Method:** Interpolation from map  
**Location Description:** The Lewis and Clark Bridge Project on HWY 85 over the Missouri River.

**Submitted By:** Ryan Hood      **Affiliation:** Johnson Bros  
**Address:** 4812 Southview Ave  
**City:** Williston      **State:** ND      **Zip:** 58801

## Received By:

**Contact Person:** Ryan Hood  
4812 Southview Ave  
Williston, ND 58801

**Distance Nearest Occupied Building:** 1 Miles      **Release Contained:** Yes

**Type of Incident:** Vibro Hammer Equipment Leak

**Description of Released Contaminant:** EcoSure Biodegradable Hydraulic Oil

**Volume Spilled:** 5.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

The Vibro Hammer equipment had a valve issue that lead to the release of hydraulic oil from the equipment.

## Risk Evaluation:

N/A - the hydraulic oil was contained on the frozen river ice, and all released oil and contaminated ice was removed from the location.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 02 - water

## Potential Environmental Impacts:

No environmental impacts anticipated. Spill was contained and everything was recovered and removed.

## Action Taken or Planned:

Immediately oil clean up pads and boom were placed on the frozen river ice to contain the oil. Personnel then used the oil pads to soak up the oil, and used shovels and buckets to remove all ice that was contaminated with oil. The buckets of contaminated ice and oil were then removed from the site to be discarded in the off site oil recycling dumpsters.

**Wastes Disposal Location:** All of the contaminated ice, and all of the oil spill, was recovered. And were taken to our oil recycling dumpsters located off site, to be recycled by Safety Kleen

**Agencies Involved:**

**Updates**

---

**Date:** 3/4/2016    **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Volume:**

**Notes:**

Follow-up required.

---

**Date:** 3/11/2016    **Status:** No Further Action Requested

**Author:** Souder, Taylor

**Updated Volume:**

**Notes:**

Observed no impacts. No further follow-up necessary at this time.