

General Environmental Incident Summary

Incident: 4083 **Date/Time Notice:** 5/4/2016 1330 **DEM Incident No:**
Responsible Party: Stericycle Speciality Waste Solutions, Inc
Date Incident: 5/3/2016 **Time Incident:** 1130 **Duration:**
County: Cass **Twp:** 139 **Rng:** 49 **Sec:** 10 **Qtr:**
Lat: 46.86259 **Long:** -96.85168 **Method:** Interpolation from map
Location Description: Back parking lot of Walgreen's store at 4201 13th Avenue South, Fargo, ND

Submitted By: Wade Van Zee **Affiliation:** Company Rep
Address: 5815 Weldon Springs Rd
City: Clinton **State:** IL **Zip:** 61727

Received By:
Contact Person: Wade Van Zee
2850 100th Ct NE
Blaine, MN 55449

Distance Nearest Occupied Building: 25 Feet **Release Contained:** Yes

Type of Incident: Lift gate hydraulic malfunction

Description of Released Contaminant: Hydraulic fluid

Volume Spilled: 1.50 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:
Lift gate hydraulic failure

Risk Evaluation:
None

of Fatalities: **# of Injuries:** **Affected Medium:** 09 - other

Potential Environmental Impacts:
None to soils or ground water

Action Taken or Planned:
Cleaned spill using floor dry and wipes

Wastes Disposal Location: Materials handled internally and are being sent to a waste to energy facility

Agencies Involved:

Updates

Date: 5/4/2016 **Status:** Reviewed - No Action Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 1.5 gallons of hydraulic fluid was spilled on the parking lot due to a lift gate malfunction. Spill was confined to an asphalt parking lot. Cass County Health will follow-up to verify no impacts to storm drains. No further action is warranted.