

# General Environmental Incident Summary

**Incident:** 4096      **Date/Time Notice:** 5/17/2016      1450      **DEM Incident No:**

**Responsible Party:** CHS

**Date Incident:** 5/17/2016      **Time Incident:** 1445      **Duration:**

**County:** Walsh      **Twp:** 157      **Rng:** 58      **Sec:** 13      **Qtr:**

**Lat:** 48.41882      **Long:** -98.07381      **Method:** Interpolation from map

**Location Description:** CHS Agronomy Center

**Submitted By:** Junell Jonasson

**Affiliation:** Safety Leader

**Address:** 515 W Montrose Ave

**City:** Milton

**State:** ND

**Zip:** 58260

## Received By:

**Contact Person:** Junell Jonasson  
515 W Montrose Ave  
Milton, ND 58260

**Distance Nearest Occupied Building:** 300 Feet

**Release Contained:** Yes

**Type of Incident:** Tank Leak

**Description of Released Contaminant:** Satellite Hydrocap

**Volume Spilled:** 3.00 gallons

**Ag Related:** Yes

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

## Cause of Incident:

worker was weighing tank to get measurement when extended plastic valve got knocked off tank.

## Risk Evaluation:

inhalation hazard

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 09 - other

## Potential Environmental Impacts:

was contained on site

## Action Taken or Planned:

product went into containment

**Wastes Disposal Location:** will wait for disposal instructions from ND Dept of AG

**Agencies Involved:** Local Emergency Manager, ND Dept of Ag

## **Updates**

---

**Date:** 5/17/2016    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

Talked to the contact who submitted the report. The spill occurred within the building and was contained within a cement containment. Floor Dry was used to clean up the liquid. The clean-up product was placed into a sealed container. The Ag Department was contacted, and the container will be collected via Project Safe Send. The workers wore respirators during cleanup.

---

**Date:** 5/20/2016    **Status:** Awaiting Documentation

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

Will send photos of the spill and post cleanup.