

General Environmental Incident Summary

Incident: 4112 **Date/Time Notice:** 5/25/2016 **DEM Incident No:**

Responsible Party: R&S Oil

Date Incident: 5/25/2016 **Time Incident:** **Duration:**

County: McLean **Twp:** 146 **Rng:** 82 **Sec:** 21 **Qtr:** NW

Lat: 47.45815 **Long:** -101.13580 **Method:** Interpolation from map

Location Description: R&S Oil Company facility located south of 3rd St NW and east of the railroad tracks.

Submitted By: Seth Wilson **Affiliation:** AECOM

Address: 800 LaSalle Ave

Suite 500

City: Minneapolis **State:** MN **Zip:** 55402

Received By:

Contact Person: Henry Rasmussen
90 Lincoln Ave
Underwood, ND 58576

Distance Nearest Occupied Building: 150 Feet **Release Contained:** No

Type of Incident: Unknown

Description of Released Contaminant: Diesel Fuel

Volume Spilled: **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

During an environmental site assessment being completed on the property by Canadian Pacific Railway, free product that appeared to be untaxed diesel fuel was encountered in a soil boring at a depth approximately 10 feet below ground surface.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 04 - water and soil

Potential Environmental Impacts:

Soil and groundwater is impacted with petroleum constituents above the NDDH action levels.

Action Taken or Planned:

No actions have been taken

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 5/25/2016 **Status:** Reviewed - Assigned to NDDoH Division

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, an unknown amount of diesel fuel was encountered during a site assessment. More follow-up needed.

Date: 5/26/2016 **Status:** Reviewed - Follow-up Required

Author: Vetter, Leon

Updated Volume:

Notes:

I requested the Phase II report be sent to me for review.

Date: 5/27/2016 **Status:** Inspection

Author: Kangas, Kathleen

Updated Volume:

Notes:

On site 05.26.16 at 11:00 a.m. 65 degrees F, sunny, light wind. Reported lat/long shows area of parking lot/yard which is north of a red building with a tin roof. Grass growth to the east shows good vegetation. Grass growth to the west of the driveway shows areas of poor vegetation. The tracks are directly west of this area. Some areas of darkened/shiny soil which may be areas of soil boring. NDDoH has requested the Phase II report for review.

Date: 5/31/2016 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Due to the contact information being incomplete or non-responsive, another number was acquired for contact. No name was given, but number is 701.315.0469 for the contact.