

# General Environmental Incident Summary

**Incident:** 4113      **Date/Time Notice:** 5/25/2016      **DEM Incident No:**

**Responsible Party:** F. U. Oil Mohall/Sherwood

**Date Incident:** 5/25/2016      **Time Incident:**      **Duration:**

**County:** Renville      **Twp:** 161      **Rng:** 84      **Sec:** 13      **Qtr:**

**Lat:** 48.76353      **Long:** -101.49750      **Method:** Interpolation from map

**Location Description:** 102 Industrial Ave, Farmers Union Oil Mohall/Sherwood

**Submitted By:** Travis Halvorson

**Affiliation:**

**Address:** 102 Industrial Ave

**City:** Mohall

**State:** ND

**Zip:**

**Received By:**

**Contact Person:**

102 Industrial Ave  
Mohall, ND

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Pipeline Leak

**Description of Released Contaminant:** Premium Diesel Fuel

**Volume Spilled:** 20.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

**Cause of Incident:**

Discovered on oil film located on top of water puddles after a rain in our west parking lot.

**Risk Evaluation:**

N/A

**# of Fatalities:**

**# of Injuries:**

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Soils located in area

**Action Taken or Planned:**

Contacted Scott Brown with Strata Corp. He is currently on site and pump truck is on way. Isolated valves at storage tank and contacted O'day equipment.

**Wastes Disposal Location:** According to Strata Corp. SOP

**Agencies Involved:**

## **Updates**

---

**Date:** 5/25/2016    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Volume:**

**Notes:**

Follow-up is required.

---

**Date:** 6/1/2016    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

Arrived on location at 10:00. 50 degrees F, cloudy, NW wind 15-25 mph. Spoke with the manager of the establishment who escorted Robin and me to the leak location and bulk tank (AST) storage area where the piping had been cut and capped. Observed an area south of the release that showed stressed vegetation. According to the manager, the Floor Dry used to soak up the release had been stockpiled in that area, and a rain event had washed some of the product onto the grass. Asked the manager to provide me with some analysis of the area to determine the vertical extent of the impact. Documentation of the cleanup and analysis will be forwarded to me or the NDDoH. More follow-up needed.

---

**Date:** 6/6/2016    **Status:** Correspondence

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

Received an email confirming that the documentation regarding the spill cleanup would be forwarded to me or the Department. Email added to folder.