

General Environmental Incident Summary

Incident: 4160 **Date/Time Notice:** 7/5/2016 0900 a **DEM Incident No:**

Responsible Party: WBT Trucking

Date Incident: 7/4/2016 **Time Incident:** 01700 pm **Duration:**

County: McKenzie **Twp:** 150 **Rng:** 98 **Sec:** 15 **Qtr:**

Lat: 47.80700 **Long:** -103.21900 **Method:** Derived from Twn Rng

Location Description: Western Area Water Supply 1/8th mile North on 1806 from 4th Street
Watford City

Submitted By: Denny Wold

Affiliation: General Manager

Address: 1905 44th Street

City: Williston

State: ND

Zip: 58802

Received By:

Contact Person: Denny Wold
1905 44th Street
Williston, ND 58802

Distance Nearest Occupied Building: 20 Feet **Release Contained:** No

Type of Incident: Tank Overflow

Description of Released Contaminant: 4 bbls of oil and fresh water

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Filling truck with fresh water and oil and fresh water came out of top of truck

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

oil and water spilled and clean up company was called in and Emergency Manager came to scene and everything was taking place that was supposed to.

Wastes Disposal Location: Hired Wolverine Clean up company and they did complete clean up

Agencies Involved: Local Emergency Manager

Updates

Date: 7/7/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Date: 7/12/2016 **Status:** Inspection

Author: Cooper, Mike

Updated Volume:

Notes:

Arrived on site at 3:30 p.m. 68 degrees, wind 15-20 mph. Walked site and took pictures of loading area.

Did not see any visible impacts within the area itself.

Noticing the drainage, I followed it down to the discharge.

The flow went into the ditch to the west. Soil removal and excavation was apparent. No visible impacts. Inspected the discharge pipe and it was clean.

Spoke with driver and he also described the incident to me. Karolyn Jappe also responded to the scene and was on site when cleanup commenced. More follow-up is needed to check on vegetative growth in the future.