

General Environmental Incident Summary

Incident: 4165 **Date/Time Notice:** 7/13/2016 **DEM Incident No:**
Responsible Party: Norsemen Trucking INC.
Date Incident: 7/13/2016 **Time Incident:** 0927 **Duration:** 5 minutes
County: Burleigh **Twp:** 139 **Rng:** 80 **Sec:** 22 **Qtr:**
Lat: 46.83657 **Long:** -100.58390 **Method:** Interpolation from map
Location Description: Driver was traveling on I-94 Eastbound close to mile marker 170, struck road debris thus damaging saddle tank and leaking diesel fuel. He stopped off at the rest area and spilled approximately 40 gallons of diesel fuel.
Submitted By: hasib rasoul **Affiliation:** transportaiton spill solutions
Address: p.o. box 1067
City: athens **State:** GA **Zip:** 30603

Received By:

Contact Person: hasib rasoul
106 Main Street
lake mills, IA 50450

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 40.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

The driver struck road debris.

Risk Evaluation:

n/a

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

The diesel fuel affected impervious asphalt parking lot and nearby soils. The soils are being excavated by Strata Corporation. The contaminated soils will be excavated at Clean Harbors

Action Taken or Planned:

Strata Corporation responded applied absorbent material over the affected parking lot. The contaminated soils are being excavated soils.

Wastes Disposal Location: Clean Harbors, Sawyer, ND

Agencies Involved: NDDDES, State Fire Marshal, State Highway Patrol, Local Fire Department, Local Law Enforcement, Local Emergency Manager

Updates

Date: 7/13/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Date: 7/14/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Volume:

Notes:

Arrived on site at 1420. This release occurred at the rest stop on I-94 eastbound headed to Fargo from Bismarck. The buildings have green roofs. The diesel leaked up the turn-off ramp and continued to the truck parking lot. The spill is on the side closest to the highway and covers about 15 by 15 feet of the parking lot. There was also some diesel that ran down to the edge of the parking lot into the grass. The grass has been scraped up there. I did not observe nor smell diesel fuel in the scraped-up area. The diesel didn't look like it ran into the ditch. The spill in the parking lot has Floor Dry over it, and the smell is evident. Further follow-up needed on Floor Dry and regrowth of grass. Photos of the spill can be found in the report folder.