

General Environmental Incident Summary

Incident: 4168 **Date/Time Notice:** 7/15/2016 **DEM Incident No:**
Responsible Party: CHS Transportation
Date Incident: 7/14/2016 **Time Incident:** 1030 **Duration:** 1 minutes
County: Mountrail **Twp:** 156 **Rng:** 92 **Sec:** 20 **Qtr:**
Lat: 48.31330 **Long:** -102.53100 **Method:** Interpolation from map
Location Description: Bakken transload facility 8836 62nd St NW

Submitted By: Eric Pearson **Affiliation:**
Address: 4115 27th Ave N
City: Grand Forks **State:** ND **Zip:** 58203

Received By:

Contact Person: ERic Pearson
4115 27th Ave N
Grand Forks, ND 58203

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Hydraulic hose leak

Description of Released Contaminant: Hydraulic Fluid

Volume Spilled: 3.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Hydraulic hose broke, leaked fluid

Risk Evaluation:

None, on concrete all material absorbed and cleaned

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

NOne

Action Taken or Planned:

absorbent pads to get initial material, floor dry to get remaining material. all on concrete pad.

Wastes Disposal Location: Shop in minot.

Agencies Involved:

Updates

Date: 7/18/2016 **Status:** Reviewed - No Action Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Release of fluid on concrete pad. Material was cleaned and disposed of. No further follow-up required.