

# General Environmental Incident Summary

**Incident:** 4185      **Date/Time Notice:** 8/2/2016      **DEM Incident No:**

**Responsible Party:** TS Bank

**Date Incident:** 8/2/2016      **Time Incident:**      **Duration:**

**County:** Divide      **Twp:** 163      **Rng:** 97      **Sec:** 29      **Qtr:**

**Lat:** 48.91325      **Long:** -103.29420      **Method:** Interpolation from map

**Location Description:** 11 E. Central Ave, Crosby, ND, 58730. South side of Bank of Tioga.

**Submitted By:** Jody Gunlock

**Affiliation:**

**Address:** 107 Central Ave

**City:** Crosby

**State:** ND

**Zip:** 58730

**Received By:** Robin Schiermeister

NDDoH

**Contact Person:** Joshua Guttau

15 E Main St.

P.O Box A

Treynor, IA 51575

**Distance Nearest Occupied Building:** 10 Feet

**Release Contained:** No

**Type of Incident:** Tank Leak

**Description of Released Contaminant:** heating oil

**Volume Spilled:**

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

## Cause of Incident:

During the renovation of the streets in Crosby they found contaminated soil which was found leaking from an underground storage tank. The tank was found to have holes which is believed to be the cause of the soil contamination.

## Risk Evaluation:

none

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 05 - air and soil

## Potential Environmental Impacts:

none

## Action Taken or Planned:

They have dug up the soil and stockpiled it by the landfill until permission is given for the soil to be cultivated into the soil.

**Wastes Disposal Location:** The contaminated soil will eventually be cultivated into soil.

## Agencies Involved:

**Updates**

---

**Date:** 8/2/2016    **Status:** No Further Action Requested

**Author:** Souder, Taylor

**Updated Volume:**

**Notes:**

Duplicate incident report