

General Environmental Incident Summary

Incident: 4204 **Date/Time Notice:** 8/20/2016 1620 **DEM Incident No:**

Responsible Party: Oneok Rockies Midstream

Date Incident: 8/20/2016 **Time Incident:** 0800 **Duration:**

County: McKenzie **Twp:** 149 **Rng:** 96 **Sec:** 4 **Qtr:**

Lat: 47.75982 **Long:** -102.97630 **Method:** Interpolation from map

Location Description: Galaxy Compressor Station
11166 24th Street NW
Watford City, ND 58854

Submitted By: Levi Weltikol

Affiliation:

Address: 896 25th St SE

City: Sidney

State: MT

Zip: 59270

Received By:

Contact Person: Levi Weltikol
896 25th St SE
Sidney, MT 59270

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Methanol

Volume Spilled: 20.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

gasket on filter blew out

Risk Evaluation:

No Immediate Risks

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

Incident was minor and contained in the immediate area. Based on the size of the spill, impacts appear limited to the immediate surface soils. no long term impacts are anticipated.

Action Taken or Planned:

Spill kits were implemented to contain the release in the building. Impacted soil will be excavated and drummed for future disposal. No further action or follow-up is planned at this time.

Wastes Disposal Location: Certified landfill

Agencies Involved:

Updates

Date: 8/22/2016 **Status:** No Further Action Requested

Author: Schiermeister, Robin

Updated Volume:

Notes:

The spill was contained on site; no further follow-up is required.

Date: 8/25/2016 **Status:** No Further Action Requested

Author: Schiermeister, Robin

Updated Volume:

Notes:

Called company representative. The release has been cleaned up and the contaminated soil excavated and disposed of at a proper facility. Photos of the area after cleanup can be found in the reports folder. No contamination can be seen from these photos. No further follow -up is needed.