

General Environmental Incident Summary

Incident: 5245 **Date/Time Notice:** 9/28/2016 1825 **DEM Incident No:**
Responsible Party: CHS Inc.
Date Incident: 9/28/2016 **Time Incident:** 1700 **Duration:** 5 minutes
County: Stark **Twp:** 140 **Rng:** 94 **Sec:** 20 **Qtr:**
Lat: 46.92141 **Long:** -102.56060 **Method:** Interpolation from map
Location Description: 100th Ave SW, Gladstone, ND

Submitted By: Gary Perowitz **Affiliation:** CHS Inc.
Address: 11 West 5th St.
PO Box 246
City: Morris **State:** MN **Zip:** 56267

Received By:

Contact Person: Delane Thom
3645 98th Ave SW
Taylor, ND 58656

Distance Nearest Occupied Building: 1 Miles **Release Contained:** No

Type of Incident: Vehicle Accident

Description of Released Contaminant: Buckaneer (glyphosate), Wheelhouse (surfactant)

Volume Spilled: 200.00 gallons **Ag Related:** Yes

EPA Extremely Hazardous Substance: No **Reported to NRC:** Yes

Cause of Incident:

Vehicle rollover accident resulting in release of product from two totes located on trailer.

Risk Evaluation:

None known

of Fatalities: 1 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None known

Action Taken or Planned:

Spill was limited to the immediate area of the vehicle located in the ditch. No water located in ditch. The impacted area was excavated on September 29 and the area restored with backfill and reseeded on September 30. AET was contracted to oversee remedial spill response activities.

Wastes Disposal Location: Excavated soils were stockpiled on and covered with plastic at the CHS Taylor Grain Terminal. A proposal has been submitted and approval received for land application of the material on CHS agricultural ground located at the facility. It is anticipated that land application will be

completed early October, 2016.

Agencies Involved: State Highway Patrol, Local Fire Department, Local Law Enforcement, Local Emergency Manager, NRC

Updates

Date: 10/3/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, 200 gallons of glyphosate and surfactant were released into a ditch along 100th Avenue SW. Further follow-up needed.

Date: 10/4/2016 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

10/4/2016 at 16:41, on location. Site is 1.1 miles north of 36th St SW along 100th Ave SW, in the west side ditch. Area has been excavated and regraded. Reseeding is evident, although with low temperatures and heavy rainfall, new growth is not expected until next growing season. Follow up in spring of 2017 to confirm regrowth in the ditch.