

Oil Field Environmental Incident Summary

Incident: RWH00000311

Date/Time of Notice: 04/17/2013 11:04

Responsible Party:

Well Operator: CLINE PRODUCTION COMPANY

Well Name: DHSU Central Site

Field Name: DICKINSON

Well File #:

Date Incident: 4/16/2013 **Time Incident:** 16:00

Facility ID Number: 401646-02

County: STARK

Twp: 140

Rng: 96

Sec: 30

Qtr: SW SW

Location Description: NW SE Sec 21-140-96.

Submitted By: Steve Simonson

Received By: Rick Hutchens

Contact Person: FRED CLINE
PO BOX 20736
BILLINGS, MT 59104

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Miles

Distance Nearest Water Well: 0.5 Miles

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	barrels	0	barrels	0	barrels
Brine	70	barrels	0	barrels	0	barrels
Other	0	barrels	0	barrels	0	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

30'x 300'

Potential Environmental Impacts:

possible SW damage to soil.

Action Taken or Planned:

They shut in wells and pipeline. Plan on scraping up oil and any contaminated soil and place on liner on DHSU #9 site until test result come back, then haul material to landfill. Expect full recovery of oil.

Wastes Disposal Location: an approved landfill.

Agencies Involved:

Updates

Date: 4/16/2013 **Status:** Inspection

Author: Nannenga, Jill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Pile of bermed contaminated material on site. Spill appears cleaned up otherwise.

Date: 4/23/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release did not remain on location, according to the report. Follow-up is necessary. Jill Nannenga is responding.